




P R E S S R E L E A S E

Annex

Diagram A





**P R E S S   R E L E A S E**

---



Photograph 1: An undamaged barge, similar to the one in the accident



Photograph 2: The Port side of the barge, with its front part damaged by the blast



**P R E S S   R E L E A S E**

---



Photograph 3: The front part of the damaged barge



Photograph 4: The view of the damaged barge from its Starboard side. The workshop is on the right side of the photograph.



**P R E S S   R E L E A S E**

---



Photograph 5: The wall panels of the workshop beside the barge were dislodged by the blast



Photograph 6: Another view of the workshop