



**Photograph showing corroded fusible plug**