

**Annex B – Photos from Worksites of Wah Khiaw Developments Pte Ltd and KG Plasterceil Pte Ltd**

**Worksite of Wah Khiaw Developments Pte Ltd**



A worker was seen performing work at the edge of the third floor of the structure, without barricades or a fall arrest system. The worker was not wearing a safety harness.



Open sides, which are edges without barricades, were observed at multiple locations at the site.



No provision of proper means of access and egress.

### Worksite of KG Plasterceil Pte Ltd



Toe-boards and guardrails were not provided on the sides of the work platform where workers could fall from more than 2 metres of height.



Workers were found working on work platforms that were not closely boarded and properly secured, which may lead to accidental displacement (i.e. shifting of the platform).



Some of the scaffold structures were erected on void areas, whereas others were placed on unstable foundations.