

**PHOTOGRAPHS SHOWING THE AREA WHERE THE FDW WAS INSTRUCTED TO
CARRY OUT HER TASKS**



There was no barricade or grille around the balcony ledge.

FDW could have fallen 10 floors.



The FDW has to stand within this narrow space when performing her tasks.