

Annex C: Photographs of Common Safety Lapses identified



Worker installing guardrails at edge of building without any fall protection



Edges of entire levels not barricaded to prevent persons from falling, as well as poor housekeeping with loose materials being placed close to the edges obstructing access



Fall protection not provided for worker



No proper work platforms for workers



Harness worn by workers did not come with lanyards and snap-hooks for securing to anchorages