
ANNEX A - COMMON SAFETY LAPSES IDENTIFIED

During MOM's WAH inspections over the last three months, common safety lapses uncovered at the construction sites included *unsecured openings without* barricades, tripping hazards, lack of proper access to and from work areas, and unsafe scaffolds.

As for the manufacturing sector, the common lapses included open sides with a lack of barriers at the sides of mezzanines floor and staircases, improper access especially the usage of ladders in poor working condition and bad housekeeping, resulting in tripping hazards.



Top 4 safety violation involving WAH uncovered