

Annex A – Photos of common safety lapses across construction and manufacturing sectors

1) Open Sides/Opening



2) Tripping Hazards



3) Unsafe access & egress



Unsecured wooden ladder



Access to workplace obstructed by materials

Unsecured decking used as access




Improper access to mezzanine floor and open sides

4) Unsafe Scaffolds



Unsecured work platforms



No toeboards or guardrails