

ANNEX A
Photos of Inspection



Photo A: Cramped sleeping area with poor maintenance.



Photo B: Cramped sleeping area with poor maintenance.



Photo C: Poor garbage disposals, leading to unsanitary living conditions.



Photo D: Unhygienic storage of cooking equipment.



Photo E: Lack of hygiene maintenance at cooking area.